Run the following installation programs as administrator (right click on the file and Run as Administrator)

🛡 18618-iccad-2016-00-win
🛡 18622-ams-2016-00-win

Don't install the license server, that is located at UNLV, see bottom. Also don't re-start your computer until you've installed both files.

Silvaco Custom IC CAD Setup ✕

Choose Destination Location
Select folder where setup will install files.

Setup will install Custom IC CAD in the following folder.

To install to this destination folder, click Next. To install to a different folder, click Browse and select another folder.

To install to a network accessible folder, click Browse and enter the network folder name (Eg. \\machine-name\share-name).

Only if this machine is to be your license server, select "Install License Server" from below.

☐ Install License Server.

Destination Folder
C:\sedatools   Browse...

InstallShield
< Back   Next >   Cancel

Silvaco AMS Setup ✕

Choose Destination Location
Select folder where setup will install files.

Setup will install AMS in the following folder.

To install to this destination folder, click Next. To install to a different folder, click Browse and select another folder.

To install to a network accessible folder, click Browse and enter the network folder name (Eg. \\machine-name\share-name).

Only if this machine is to be your license server, select "Install License Server" from below.

Only if this machine is to be your Database server, select "Install Database Server" from below.

☐ Install License Server.   ☐ Install Database Server.

Destination Folder
C:\sedatools   Browse...

InstallShield
< Back   Next >   Cancel

Start the SFLM access in the S. EDA Tools folder (perhaps a short cut on your desktop).

And add the license server as seen below. Get address of the server from one of the other students or Dr. Baker.

Restart your computer. The Silvaco tools are installed!